





Vacuum pump condition inspection :

- Vanes found has been warn out
- cylinder has severe scratch marks
- Excessive wear at filtration and exhaust area
- Bearings damaged











































































All pumps re-installed and inspected :

- Perfectly working and system back to operational as it should

- Performance test carried out and the vacuum generates extremely fast



ASH MANN VACUUM SERVICES SDN BHD Letter Box 5, Room 1203,12th Floor, Wisma Pahlawan,Jalan Sultan Sulaiman, 5000 Kuala Lumpur, Malaysia Tel.: +60162056189 , +60163416189, +60167743229 E-mail: contact@ashmannservices.com Website:www.ashmannservices.com