







Very low on suction – valve opened and checked for blockage



Valve working perfectly fine



It was plastic , stone and debris found stuck at the bottom of collection sump
Cleared with provided maintenance tools



Controller sn: 112519093 Installation complete

CC04 Controller installation works



Source of blockage removed



Chamber washed clean and dried



Controller sn: 112519092 Installation complete

CC07 Controller installation works





Controller sn: 112519095 Installation complete

CC10 Controller installation works





Controller sn: 112519094 Installation complete



**Aqseptence
Group**

ASH MANN VACUUM SERVICES

Letter Box 5, Room 1203, 12th Floor,
Wisma Pahlawan, Jalan Sultan Sulaiman,
5000 Kuala Lumpur, Malaysia
Tel.: +60162056189 , +60163416189, +60167743229
E-mail: contact@ashmannservices.com
Website: www.ashmannservices.com