

Discharge pumps overhauling works



Ashmann Vacuum Services Sdn Bhd has point out that the discharge pumps are no longer efficient enough to couple up with the system .We received several reports on poor sewage discharging issues from vacuum vessel and client has ordered us to get the discharge pumps overhauled.









Pump Impeller replaced



Pump ready for test runs



Pump passed leak tests under pressurized condition (gasket sits perfectly)
- Flow test passed



Pumps repainted and sent to site



Both discharge pumps perfectly installed



Pumps are in best working condition , full flow in pipeline



ASH MANN VACUUM SERVICES SDN BHD

Letter Box 5, Room 1203, 12th Floor,
Wisma Pahlawan, Jalan Sultan Sulaiman,
5000 Kuala Lumpur, Malaysia
Tel.: +60162056189 , +60163416189, +60167743229
E-mail: contact@ashmannservices.com
Website: www.ashmannservices.com