

Chamber pod self-evacuation unit installation works

And broken 8/R 3/8" adapter replaced



Flooded chamber washed clean




Broken 8/R 3/8" adapter replaced



Chamber pod self-evacuation unit



Chamber pod self-evacuation unit properly installed , this will eliminate any water ponding in pod due to heavy rain



Chamber pod self-evacuation design drawing



**Aqseptence
Group**

ASH MANN VACUUM SERVICES SDN BHD

Letter Box 5, Room 1203, 12th Floor,
Wisma Pahlawan, Jalan Sultan Sulaiman,
5000 Kuala Lumpur, Malaysia
Tel.: +60162056189 , +60163416189, +60167743229
E-mail: contact@ashmannservices.com
Website: www.ashmannservices.com